





Earth 522 Pedalboard Power Supply Installation Guide



V1 & V2 for Voodoo Lab Power Supplies [Mondo, 4x4, 2Plus]

C1 & C2 for Cioks Power Supplies [Ciokolate, DC10, DC8]

W1, W2, W3, W4 for Walrus Audio Power Supplies [Phoenix, Aetos]



Installation Guide for Voodoo Lab Power Supply

For Voodoo Lab Mondo:

1. Remove the side screws from the power supply and use those screws to mount the power supply with the brackets on V1 & V2 of the brackets.
2. Remove the underneath pedalboard screws 1A, 1B, 4A, 4B and use those screws to mount the brackets (& power supply) underneath the pedalboard on the 1A, 1B, 4A, 4B positions.

For Voodoo Lab 4x4:

1. Remove the side screws from the power supply and use those screws to mount the power supply with the brackets on V1 & V2 of the brackets.
2. Remove the underneath pedalboard screws 2A, 2B, 4A, 4B and use those screws to mount the brackets (& power supply) underneath the pedalboard on the 2A, 2B, 4A, 4B positions.

For Voodoo Lab Pedal Power 2 Plus:

1. Remove the side screws from the power supply and use those screws to mount the power supply with the brackets on V1 & V2 of the brackets.
2. Remove the underneath pedalboard screws 3A, 3B, 4A, 4B and use those screws to mount the brackets (& power supply) underneath the pedalboard on the 3A, 3B, 4A, 4B positions.





Installation Guide for Cioks Power Supply

For Cioks Ciokolate:

1. Remove the side Screws of the power supply.
2. Remove the underneath pedalboard screws 1A, 1B, 2A, 2B, 5A, 5B, 6A, 6B totally 8 screws.
3. Use 4 screws removed from the pedalboard to mount the power supply with the brackets on C1 & C2 of the brackets.

4 Use the other 4 screws to mount the brackets (& power supply) underneath the pedalboard on the positions 2A, 2B, 6A, 6B or 1A, 1B, 5A, 5B

For Cioks DC10:


1. Remove the side Screws of the power supply.
2. Remove the underneath pedalboard screws 2A, 2B, 3A, 3B, 4A, 4B, 5A, 5B totally 8 screws.
3. Use 4 screws removed from the pedalboard to mount the power supply with the brackets on C1 & C2 of the brackets.

4 Use the other 4 screws to mount the brackets (& power supply) underneath the pedalboard on the positions 3A, 3B, 4A, 4B

For Cioks DC8:

1. Remove the side Screws of the power supply.
2. Remove the underneath pedalboard screws 2A, 2B, 3A, 3B, 4A, 4B, 5A, 5B totally 8 screws.
3. Use 4 screws removed from the pedalboard to mount power supply with the brackets on C1 & C2 of the brackets.

4 Use the other 4 screws to mount the brackets (& power supply) underneath the pedalboard on the positions 3A, 3B, 4A, 4B





Installation Guide for Walrus Audio Supply

For Walrus Audio Phoenix:

1. Remove the bottom Screws of the power supply.
2. Remove the underneath pedalboard screws 3A, 3B, 4A, 4B, 5A, 5B, 6A, 6B totally 8 screws.

3. Use 4 screws removed from the pedalboard to mount power supply with the brackets on W3 & W4 of the brackets.

4 Use the other 4 screws to mount the brackets (& power supply) underneath the pedalboard on the positions 3A, 3B, 6A, 6B

For Walrus Audio Aetos:

1. Remove the bottom Screws of the power supply.

2. Remove the underneath pedalboard screws 1A, 1B, 3A, 3B, 4A, 4B, 6A, 6B totally 8 screws.

3. Use 4 screws removed from the pedalboard to mount power supply with the brackets on W2 & W4 of the brackets.

4 Use the other 4 screws to mount the brackets (& power supply) underneath the pedalboard on the positions 4A, 4B, 6A, 6B or 1A, 1B, 3A, 3B